LOCAL NOTICE TO MARINERS

COASTAL WATERS FROM EASTPORT, MAINE TO SHREWSBURY, NEW JERSEY

WEEKLY SUPPLEMENT

OO INTERNET ADDRESS OO

HTTP://www.navcen.uscg.mil

FTP://ftp.navcen.uscg.mil

Weekly supplemental editions contain new information only available following the monthly edition. NOTE: Chart corrections and Light List changes appear only once each. A complete listing of current discrepancies and temporary changes appear in the monthly issue, LNM 05/00. Subscription to this weekly publication is free. If you have questions about the LNM or wish to be on the mailing list, contact:

COMMANDER, FIRST COAST GUARD DISTRICT (oan)

408 Atlantic Avenue, Boston, Massachusetts 02110-3350

Telephone (Day): 1-800-848-3942. To order LNM: Ext. 8335 (After 4:30 p.m. Ext. 7722) 24 Hour FAX: (617) 223-8073

Coast Guard's Customer Infoline (8:00 a.m. - 4:00 p.m.): 1-800-368-5647.

Hearing impaired (TDD) 1-800 689-0816

All bearings are in degrees TRUE - All times are in Local Time unless otherwise noted.

NOTE: A vertical line in the RIGHT MARGIN of sections I, V, VI, VII indicates new information.

BROADCAST NOTICE TO MARINERS

The following Broadcast Notice to Mariners (BNM's) have been issued since last week:

First District	CG1- 0030	to	0037
Group Boston	BOS- 0013	to	0020
Group Long Island Sound	LIS- 0027	to	0032
Group Moriches	MOR- 0020	to	0027
Group New York	NEW- 0043	to	0049
Group Portland	POR- 0007	to	0009
Group Southwest Harbor	SWH- 0011	to	0019
Group Woods Hole	WHO- 0036	to	0049

Light List Reference: ATLANTIC COAST, VOLUME 1, COMDTPUB P16502.1, 1999 Edition

I SPECIAL NOTICES This section contains information of Special concern to the Mariner.

NONE THIS WEEK

II DISCREPANCIES This section lists all discrepancies to Aids to Navigation reported and corrected since the last published list. A discrepancy is a change in the status of an aid to navigation that differs from what is published and or charted.

DISCREPANCIES (since last week)

			Chart	BNM	LNM	
LLNR	Name of Aid	Status	Affected	Ref.	Ref.	
45	PORTLAND LHB P	RAC INOP	13003	CG1-0039-00	06/00	
2245	CLARK PT DBN 1	MISSING	13321	SWH-0020-00	06/00	
12635	DUXBURY BAY CH BY 11	MISSING	13253	BOS-0019-00	06/00	
15780	WOODS HOLE PASS BY 1	OFF STA	13235	WHO-0048-00	06/00	
15785	WOODS HOLE PASS BY 2	OFF STA	13235	WHO-0049-00	06/00	
19375	WARWICK COVE BY 7	OFF STA	13221	WHO-0045-00	06/00	
19405	GREENWICH BAY BY 6	OFF STA	13224	WHO-0046-00	06/00	

19410	GREENWICH BAY BY 7	OFF STA	13221	WHO-0041-00	06/00
22120	UPPER THAMES RV CH BY 15	OFF STA	12372	LIS-0032-00	06/00
23480	CLINTON HBR CH BY 8	MISSING	12374	LIS-0028-00	06/00
23485	CLINTON HBR CH BY 9	MISSING	12372	LIS-0029-00	06/00
23490	CLINTON HBR CH BY 11	MISSING	12374	LIS-0030-00	06/00
23495	CLINTON HBR CH BY 11A	MISSING	12372	LIS-0031-00	06/00
26425	EATONS NECK BY 2	OFF STA	12365	LIS-0027-00	06/00
27785	THREEMILE HBR ENT BY 2	OFF STA	12354	MOR-0021-00	06/00
28240	SHELTER IS SND S CH BY 3	OFF STA	13209	MOR-0023-00	06/00
28295	SHELTER IS SND S CH BY 8	MISSING	12354	MOR-0022-00	06/00
29145	FIRE IS IN CH LB 8	OFF STA/LT IMCH	12352	MOR-0025-00	06/00
30291	MORICHES BAY LB 10	HAZ NAV/BUOYSINK	12352	MOR-0026-00	06/00
31015	WEST END BOAT BASIN BY 1	OFF STA	12352	MOR-0027-00	06/00
31105	SLOOP CH DBN 35	MISSING	12352	MOR-0024-00	06/00
DISCREPANCI	ES CORRECTED				
			Chart	BNM	LNM
LLNR	Name of Aid	Status	Affected	Ref.	Ref.
1305	EMMS RK LT 9	WATCHING PROPERLY	13325	SWH-0017-00	06/00
1855	TURTLE IS LDG GB 2	RESET ON STATION	13322	SWH-0012-00	05/00
1855	TURTLE IS LDG GB 2	WATCHING PROPERLY	13312	SWH-0016-00	06/00
3520	HEWES LDG BY 2	WATCHING PROPERLY	13309	SWH-0019-00	06/00
3930	FOX ISLANDS THOROFARE LB 16	WATCHING PROPERLY	13308	SWH-0013-00	06/00
4435	ISLESBORO IS LBB II	WATCHING PROPERLY	13302	SWH-0007-00	03/00
5485	THE CUCKOLDS LT	WATCHING PROPERLY	13260	POR-0008-00	06/00
7540	PORTLAND HBR EASTERN APP LB 3	WATCHING PROPERLY	13290	POR-0009-00	06/00
8270	YORK HBR BY 4	WATCHING PROPERLY	13278	POR-0001-00	03/00
8406	KITTERY FLATS TURN BASIN BY A	WATCHING PROPERLY	13285	POR-0005-00	04/00
8825	SAGAMORE CREEK BY SL	WATCHING PROPERLY	13283	POR-0007-00	05/00
9300	PLUM IS SND ENT LBB 2	WATCHING PROPERLY	13274	BOS-0015-00	05/00
9655	ANNISQUAM RIV CH BY 14	WATCHING PROPERLY	13281	BOS-0020-00	06/00
10680	BOSTON N CH ENT LWB NC	WATCHING PROPERLY	13200	BOS-0017-00	06/00
10985	CHELSEA RIV CH LB 6	WATCHING PROPERLY	13272	BOS-0021-00	06/00
11825	TOWN RIVER BAY CH BY 2	WATCHING PROPERLY	13270	BOS-0013-00	05/00
11835	TOWN RIVER BAY CH BY 4	WATCHING PROPERLY	13270	BOS-0014-00	05/00
11840	TOWN RIVER BAY CH BY 6	WATCHING PROPERLY	13270	BOS-0013-00	05/00
12650	DUXBURY BAY CH BY 14	WATCHING PROPERLY	13253	BOS-0013-00 BOS-0018-00	05/00
12910	PLYMOUTH HBR CH LBB 9	WATCHING PROPERLY	13246	BOS-0018-00 BOS-0009-00	06/00
13140	SESUIT HBR APP LBB 1S	WATCHING PROPERLY	13246	WHO-0024-00	06/00
13535	POLLOCK RIP CH LGB 4	WATCHING PROPERLY	13237	WHO-0036-00	05/00
14050	SAQUATUCKET HBR E JTY LT 6	WATCHING PROPERLY	13229	WHO-0030-00	06/00
14065	WYCHMERE HBR JTY LT 1	WATCHING PROPERLY	13229	WHO-0043-00	06/00
15755	BROADWAY BY 1	WATCHING PROPERLY	13229	WHO-0044-00	06/00
				WHO-0018-00	
15790	WOODS HOLE PASS JCT BY SB	WATCHING PROPERLY	13235		06/00
16082	BIRD IS REEF BB 17	WATCHING PROPERLY	13236	WHO-0040-00	06/00
16220	HOG IS CH LBB 18	WATCHING PROPERLY	13229	WHO-0037-00	05/00
16525	SOUTHWEST LDG BY 10	WATCHING PROPERLY	13236	WHO-0033-00	05/00
17385	BUTTERMILK BAY APP BY	WATCHING PROPERLY	13229	WHO-0013-00	06/00
17405	BUTTERMILK BAY APP BY 5	WATCHING PROPERLY	13236	WHO-0047-00	06/00
19720	BLOCK IS BKW LT 3	WATCHING PROPERLY	13217	WHO-0009-00	06/00
19805	WATCH HILL LWB WH	WATCHING PROPERLY	13215	WHO-0008-00	04/00
21040	WEST HARBOR CH LB 6	WATCHING PROPERLY	13214	LIS-0025-00	05/00
21155	SIXMILE REEF LBB 8C	WATCHING PROPERLY	12354	LIS-0015-00	03/00
24230	QUINNIPIAC RIV BY 1	WATCHING PROPERLY	12371	LIS-0026-00	05/00
24615	BRIDGEPORT HBR LT 13A	WATCHING PROPERLY	12363	LIS-0014-00	03/00
29220	FARM SHOALS CH LB 5	WATCHING PROPERLY	12352	MOR-0011-00	04/00
29240	EAST CH JCT LB EW	WATCHING PROPERLY	12352	MOR-0008-00	04/00
30291	MORICHES BAY LB 10	SEE ABOVE	12352	MOR-0017-00	05/00
34405	BEACH CH LB 5	WATCHING PROPERLY	12350	NEW-0043-00	06/00
35170	SANDY HOOK CH LBB 16	WATCHING PROPERLY	12324	NEW-0045-00	06/00
35520	SANDY HOOK PT OBST BY 1	WATCHING PROPERLY	12401	NEW-0046-00	06/00
36960	BAY RIDGE ANCH LB C	WATCHING PROPERLY	12327	NEW-0048-00	06/00
37240	LIBERTY IS CH BY 2	WATCHING PROPERLY	12335	NEW-0047-00	06/00
37265	KILL VAN KULL CH JCT LBB KV	WATCHING PROPERLY	12327	NEW-0049-00	06/00
37325	BERGEN PT LT 14	RELIGHTED/TRLB	12333	NEW-0040-00	05/00
37335	KILL VAN KULL CH LB 16	WATCHING PROPERLY	12327	NEW-0044-00	06/00
	ES (PRIVATE AIDS)				
DISCREI AINCL	LO (IMVAIL AIDO)		Chart	BNM	LNM
LLNR	Name of Aid	Status	Affected	Ref.	Ref.
27795	THREEMILE HBR W BREAKWTER LT		13209	MOR-0020-99	20/99
41173	I TREEWILE HOR W DREAKWIEK LI	EAI	13209	MOK-0020-99	20/99

DISCREPANCIES (PRIVATE AIDS) CORRECTED

Chart BNM LNM
LLNR Name of Aid Status Affected Ref. Ref.

NONE THIS WEEK

III TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED This section contains temporary changes and corrections to Aids to Navigation for the current week. When aids are temporarily relocated for dredging, a temporary correction shall be listed in Section IV giving the new position.

TEMPORARY	CHANGES				
LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
		NONE THIS WEEL	K		
TEMPORARY CHANGES CORRECTED					
TEMPORAR	Y CHANGES CORRECTED				
TEMPORAR	Y CHANGES CORRECTED		Chart	BNM	LNM
TEMPORAR'	Y CHANGES CORRECTED Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.

IV CHART CORRECTIONS

This section contains corrections to federal and private maintained Aids to Navigation, as well as NOS corrections.

This section contains corrective actions affecting chart(s). Corrections appear numerically by chart number, and pertain to that chart only. The mariner must decide which Chart(s) to correct. The following example explains the individual elements of a typical chart correction.

Chart	Chart	Edition	Last Local Notice	Horizontal	Source of	Current Local
Number	Edition	Date	to Mariners	Datum Reference	Correction	Notice to Mariners
ullet	ullet	•	4	•	•	↓
12327	91st Ed.	04/19/97	LAST LNM 26/97	NAD 83	(CG1)	27/97
(TEMP) NY	Y-NJ-NEW Y	ORK HARBOR	- RARITAN RIVER			
Add	National I	Oock Channel Buo	y 3, green can			40°41'09.0"N 074°02'48.1"W
^		^				^
Corrective	Object of	corrective				Position

Action Action (Degrees, minutes, seconds and tenths)
The letter (M) immediately following the chart number indicates that the correction should be applied to the Metric side of the chart only. (Temp) Indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (NM).

13270 58th ed.,.10/09/99 LAST LNM 05/00 NAD 83	06/00
BOSTON HARBOR	NOS SILVER SPRING
CHANGE depth legend to: 12 FT FOR WIDTH OF 100 FT NOV 1997	42-17-48.300N 071-02-34.700W
depth legend to: 13 FT FOR WIDTH OF 175FT NOV 1997	42-18-23.600N 071-02-14.700W
12372 29th ed., 07/19/97 LAST LNM 02/00 NAD 83	06/00
WATCH HILL TO NEW HAVEN HARBOR - LONG ISLAND SOUND	CGD01
DELETE Upper Thames River Wreck LB WR20A	41-27-41.162N 072-04-05.748W
13283 17th ed., 04/11/1998 LAST LNM 22/99 NAD 83	06/00
PORTSMOUTH HARBOR CAPE NEDDICK HARBOR TO ISLES OF SHOALS	CGD01
RELOCATE Badgers Island Buoy 14 from 43-04-51.088N 070-45-20.671W to	43-04-51.951N 070-45-21.518W
13285 9th ed., 05/02/1998 LAST LNM 01/99 NAD 83	06/00
PORTSMOUTH TO EXETER	CGD01
RELOCATE Badgers Island Buoy 14 from 43-04-51.088N 070-45-20.671W to	43-04-51.951N 070-45-21.518W

V ADVANCE NOTICES This section contains advance notice of approved projects or upcoming temporary changes such as dredging, etc. Mariners are advised to use caution while transiting these areas.

SU	MMARY OF ADVANCED APPROVED PROJECTS	
WATERWAY	Project Date	Ref. LNM
MA/BUTTERMILK APPROACH	29 FEB 2000	06/00
MA/MATTAPOISETT HARBOR	29 FEB 2000	06/00
NY/NEW YORK HARBOR	5 MAR 2000	02/00

MA – NANTUCKET SOUND AND APPROACHES – NANTUCKET SOUND MAIN CHANNEL – The Coast Guard will be making the following change to Aids to Navigation on or about 21 February 2000 to improve the operating efficiency of the light:

Change West Chop Light (LLNR 13775) from 15 NM white and 11 NM red to 14 NM white and 11 NM red. Chart(s) 13233, 13229, 13237 LNM 06/00 (CGD1)

MA – MARTHA'S VINEYARD TO BLOCK ISLAND – VINEYARD SOUND – The Coast Guard will be making the following change to Aids to Navigation on or about 21 February 2000 to improve the operating efficiency of the light:

Change Nobska Point Light (LLNR 15560) from 16 NM white and 12 NM red to 13 NM white and 11 NM red.

Chart(s) 13235, 13230, 13229, 13218 LNM 06/00 (CGD1)

MA – MARTHA'S VINEYARD TO BLOCK ISLAND SOUND – BUZZARDS BAY - The Coast Guard will be making the following changes to Aids to Navigation on or about 01 March 1999 to facilitate navigation through this waterway:

Change Seventeen-Foot Ledge Lighted Buoy 1 (LLNR 16000) to Buzzards Bay Lighted Buoy 1 (LLNR 16000), FI G 2.5s light characteristic.

Change Thirty-Foot Spot Lighted Bell Buoy 2 (LLNR 16005) to Buzzards Bay Lighted Bell Buoy 2 (LLNR 16005).

Change Hen and Chickens Lighted Gong Buoy 3 (LLNR 16010) to Buzzards Bay Lighted Gong Buoy 3 (LLNR 16010).

Change Coxens Ledge Lighted Bell Buoy 4 (LLNR 16025) to Buzzards Bay Lighted Bell Buoy 4 (LLNR 16025).

Change Mishaum Ledge Lighted Gong Buoy 5 (LLNR 16035) to Buzzards Bay Lighted Gong Buoy 5 (LLNR 16030), Fl G 6s light

characteristic

Change Penikese Lighted Bell Buoy 6 (LLNR 16030) to Buzzards Bay Lighted Bell Buoy 6 (LLNR 16035).

Change Wilkes Ledge Lighted Buoy 7 (LLNR 16045) to Buzzards Bay Lighted Buoy 7 (LLNR 16045) and relocate to PA 41-30-25.0N, 070-54-

10 OW

Change Traffic Lighted Gong Buoy 8 (LLNR 16050) to Buzzards Bay Lighted Gong Buoy 8 (LLNR 16050) and relocate to PA 41-28-57.6N,

070-53-50.0W

Change Bird Island South Shoal Gong Buoy 15 (LLNR 16081) to Bird Island Gong Buoy 1 (LLNR 16081).

Change Bird Island Reef Bell Buoy 17 (LLNR 16082) to Bird Island Bell Buoy 3 (LLNR 16082).

Chart(s) 13218, 13230 LNM 06/00 (CGD1)

ME – TIBBETT NARROWS TO SCHOODIC ISLAND - The Coast Guard will be making the following changes to an Aids to Navigation to facilitate navigation through Corea Harbor on or about 30 April 00:

Change Wash Rock Ledge Gong Buoy 3 (LLNR 1800) to Wash Rock Ledge Gong Buoy 2

(LLNR 1800), Red and relocate to PA 44-23-12N, 067-57-42W, approx. 100 yards SE of rock.

Chart(s) 13324, 13312 LNM 06/00 (CGD1)

VI PROPOSED CHANGES

This section contains notice of non approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to: Commander, First Coast Guard District (oan), 408 Atlantic Avenue, Boston, MA 02110-3350, unless otherwise noted.

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT					
WATERWAY	Closing	Docket No.	Ref. LNM		
MA/NANTUCKET SOUND	15 Feb 2000	01-98-10	01/00		
MA/MASS BAY-					
RI/NANTUCKET SHOALS	28 Feb 2000	N/A	50/99		
NY/SEACOAST	29 Feb 2000	01-99-26	50/99		
NY/BROTHERS ISLAND CHANNEL	14 Feb 2000	01-00-00	02/00		
NY/BUTTERMILK CHANNEL	29 Feb 2000	01-00-02	03/00		

LORAN-C OPERATIONS, LORSTA NANTUCKET (RATE 9960-X/5930-X) - This is a proposal to authorize LORSTA Nantucket (rate 9960-X/5930-X) unusable time from 1300Z to 1500Z on 07 Mar 2000. The alternate time will be from 1300Z to 1500Z on 08 Mar 2000. Objections will be considered until 1500Z 02 Mar 2000. Users shall address inquiries to the Northeastern U. S. Loran-C Chain Operations Control Officer (POC: Lt.Bob Feigenblatt) at (703) 313-5887/5900. Current Loran-C status is available 24 hrs/day through internet address: http://www.navcen.uscg.mil, ftp://ftp.navcen.uscg.mil. LNM 06/00 (CGD1)

LORAN-C OPERATIONS, LORSTA SENECA (RATE 9960-M/8970-X) - This is a proposal to authorize LORSTA Seneca (rate 9960-M/8970-X) unusable time from 1400Z to 1600Z on 04 April 2000. The alternate time will be from 1400Z to 1600Z on 05 April 2000. Objections will be considered until 1600Z 31 March 2000. Users shall address inquiries to the Northeastern U. S. Loran-C Chain Operations Control Officer (POC: Lt Bob Feigenblatt) at (703) 313-5887/5900. Current Loran-C status is available 24 hrs/day through internet address: http://www.navcen.uscg.mil, ftp://ftp.navcen.uscg.mil, LNM 06/00 (CGD1)

ME – SOMES SOUND APPROACH - The Coast Guard is considering making the following changes to Aids to Navigation in this waterway to improve navigation through Somes Sound Approach:

Change Cranberry Island Ledge Buoy 4 (LLNR 2265) to Cranberry Island Ledge Lighted Buoy 4 (LLNR 2265) Red,

Fl R 2.5s, 4NM nominal range

Change Cow Ledge Buoy 6 (LLNR 2275) to Spurling Point Lighted Buoy 6 (LLNR 2275) Red, Fl R 4s, 3NM nominal range and relocate to PA

44-15-44.0N, 068-16-46.3W

Delete Somes Harbor Buoy 9 (LLNR 2215)

DeleteWestern Way Lighted Bell Buoy "WW" (LLNR 2260).DeleteSpurling Point Lighted Gong Buoy "SP" (LLNR 2280).

Delete Spurling Point Buoy 8 (LLNR 2285).

Interested mariners are strongly encouraged to comment on this proposal in writing, either personally or through their organization. All comments shall be carefully considered and are requested prior to 13 MAR 00 to facilitate the process. Refer to Docket No. 01-00-03. In addition to the address listed on the front cover, e-mail can be sent to: mrudick@dl.uscg.mil and faxes to (617) 223-8073.

Chart(s): 13321, 13318, LNM 06/00 (CGD1)

VII GENERAL

This section contains information of general concern to the mariner. Mariners are advised to use caution while transiting these areas.

SUMMARY OF EFFECTIVE DREDGING/CONSTRUCTION OPERATIONS

The following is a listing of marine construction and dredging projects still in effect in the First District. All mariners are advised to use caution in these areas. The LNM REF column refers to the LNM in which the article first appears and where detailed information may be obtained. The dates listed for completion are tentative. An asterisk in the left margin marks new information.

LOCATION	SUBJECT	COMPLETION DATE	LNM REF
NJ/HACKENSACK RIVER	Dredging	28 Feb 2000	03/00
RI/PROVIDENCE RIVER	Drilling holes	February 2000	45/99
NY/NJ/ARTHUR KILL	Dock Repairs	February 2000	42/99
NY/ERIE BASIN	Channel wall construction	February 2000	47/99
MA/WINTHROP	Dredging	15 Feb 2000	37/99
MA/SCITUATE	Dredging	15 Feb 2000	51/99
NY/JAMAICA BAY CROSSING	Substructure repairs	March 2000	47/99
NJ/BAYONNE	Pier construction	20 Mar 2000	42/99
NY/KILL VAN KULL	Dredging	15 June 2000	21/99
NY/BROOKLYN	Pier reconstruction	June 2000	26/99
NY/BROOKLYN	Dock modifications	June 2000	28/99
NY/NJ/ KILL VAN KULL	Disposal operations	September 2000	35/99
NY/BROOKLYN	Pier repairs	March 2001	39/99
NY/KILL VAN KULL	Dredging	2004	28/99
NY/BROOKHAVEN	Cable laying	Until further notice	37/99
NY/NEW YORK HARBOR	Project to measure Dissolved Oxygen	Until further notice	42/99
NY/LONG ISLAND	Cable repairs	Until further notice	44/99
MA/MARTHA'S VINEYARD	Cable retrieval/repair	Until further notice	50/99

US SEACOAST – NY/NJ - HAZARD TO NAVIGATION - The cable laying vessel MAERSK FORWARDER is engaged in 24 hour cable laying operations in the vicinity of Manasquan Inlet offshore to a depth of 1000 fathoms in approximate position 40-05.0N 073-50.0W seaward to 39-45.0N 072-30.0W. Operations commenced 04 February 2000 and continue until 06 April 2000. These operations include underwater vehicles astern, dive operations and limited maneuvering capabilities. All vessels are to give a wide berth and to remain well clear at all. MAERSK FORWARDER monitors VHF channels 16 and 13

Chart(s) 12300, 13003, 13006 LNM 06/00 (CGD1)

MA - BOSTON HARBOR – (Revised) - Pier work is being conducted at the Boston Coast Guard Base from 01 Feb to approximately 01 Jun, 2000. Mariners are reminded that this is NO WAKE ZONE and to proceed with caution while transiting the area. Chart(s) 13270 LNM 06/00 (CGD1)

BRIDGE SECTION						
BRIDGE	TYPE	WATERWAY	NM	SUBJECT	REF/LNM	
Carlton	F	Kennebec River	14.1	Bridge Construction	52-99	
Summer Street Bridge	R	Reserved Channel	0.9	Bridge Construction	52-99	
I-93 Main Line	F	Charles River	0.6	Bridge Construction	05-00	
Brightman Street	В	Taunton River	2.1	Bridge Construction	05-00	
Rt 3A	В	Weymouth Fore River	2.8	Bridge Construction	47-99	
Mount Hope	F	Mount Hope Bay	0.0	Bridge Rehabilitation	47-99	
Old Providence Road	F	Palmer River	0.7	Bridge Construction	05-00	
I-95	F	Pequonnock River	0.0	Bridge Replacement	01-00	
Tomlinson	В	Quinnipiac River	0.0	Bridge Replacement	47-99	
Grand Street	В	Pequonnock River	0.9	Bridge Demolition	46-99	
Route 1 (Singing)	F	Patchogue River	0.6	Bridge Rehabilitation	05-00	
Goethals	F	Arthur Kill	11.5	Barge Placement	49-99	
Brooklyn	F	East River	0.8	Emerg. Deck Repairs	52-99	
Manhattan Bridge	F	East River	1.1	Bridge Rehabilitation	05-00	
Queensboro/59 th Street	F	East River	5.5	Vert. Clear. Reduction	52-99	
Robert Moses Causeway	F	Great South Bay	7.3	Bridge Rehabilitation	50 99	
Third Avenue Bridge	SW	Harlem River	1.9	Bridge Closure	45-99	
Macombs Dam Bridge	SW	Harlem River	3.2	Bridge Rehabilitation	04-00	
George Washington	F	Hudson River	11.0	Bridge Rehabilitation	05-00	
Tappan Zee	F	Hudson River	27.0	Bridge Rehabilitation	47-99	
Tappan Zee	F	Hudson River	27.0	Vert. Clear. Reduction	05-00	
Castleton	F	Hudson River	135.7	Vert. Clear. Reduction	51-99	
Marine Parkway	VL	Jamaica Bay	3.0	Vert. Clear. Reduction	01-00	
Beach Channel	SW	Jamaica Bay	6.7	Bridge Rehabilitation	50-99	
Atlantic Beach	В	Reynolds Channel	0.4	Bridge Rehabilitation	50 99	
Route 35	F	Navesink River	8.3	Bridge Replacement	47-99	
Eighth Street	F(B)	Passaic River	15.3	Bridge Construction	46-99	
NJ Turnpike	F	Rahway River	2.0	Bridge Repairs	46-99	

NJ Turnpike	F	Rahway River	2.0	Bridge Painting	02-00
Route 9	F	Raritan River	2.1	Bridge Replacement	03-00

KEY: F-Fixed SW-Swing R-River C-Canal CK-Creek B-Bascule VL-Vertical Lift Ch-Channel Hbr-Harbor Th-Thoroughfare NM-Nautical mile.

APPLICATION HAS BEEN RECEIVED FOR COAST GUARD APPROVAL OF THE FOLLOWING BRIDGE REGULATION CHANGE:

BRIDGE US1 (Gi			RULE# 117.605	COMMENT PERIOD ENDS 7 March 2000			REF/LNM 04/00
	IGHT LIST CORRECTION IN WITH A STREET THE ST		has been made or new	v informati	on added.		
(1) No.	(2) Name and location	(3) Position	(4) Characteristic	(5) Ht	(6) Rng	(7) Structure	(8) Remarks
11885	Weymouth Back River - Channel Lighted Buoy 1	42 15.9 70 55.8 *	Fl G 2.5s		3	Green.	Replaced by LIB from Dec. 1 to Apr. 15. 06/00